

DATE 1950Z 27 SEPT 61

SECRET

1	4
2	5
3	6

TO : DIRECTOR

25X1A

FROM : [REDACTED]

ACTION: DPD (1,2,3,4,5,6,7,8,9,10)

INFO : S/C (11)

EG

25X1A

TOR: 2039Z 27 SEPT 61

ROUTINE

IN 18722

TO [REDACTED]

INFO

CITE

2062

REF A. [REDACTED] 1532 (IN 07767)

25X1A

25X1A B. [REDACTED] 3692 (OUT 00014)

FOR [REDACTED]

25X1A

1. ARTICLE 378 HAS BEEN MODIFIED TO REMOVE THE SLIPPER TANK FLOAT VALVE PER REFERENCE A, PARA 2. RESULTS WERE SATISFACTORY.

2. S/B 557 HAS BEEN ISSUED TO REMOVE THE FLOAT VALVE, ADD CHECK VALVES, AND ROTATE THE SNIFFLE VALVES. THIS WILL APPLY TO ALL ARTICLES WITH SLIPPERS.

3. IN VIEW OF ABOVE, ECP 97 SHOULD BE CANCELLED, ALTHOUGH TO SLIPPER STRIPPER PUMPS WERE PROCURED FOR ANTICIPATED TESTS BUT WERE NOT USED.

END OF MESSAGE

DOCUMENT NO.

NO CHANGE IN CLASS. (1)

EX-100 CLASSIFIED

CLASSIFICATION TO: TS S

NEXT REVIEW DATE:

AUTH: HR 70-2

DATE: 2/12/81 REVIEWER: [REDACTED]

25X1A

25X1A